



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: 4/6/15

WEATHER: 65°F, A Few clouds

INSPECTED BY: D. West, K. Homza

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	✓	✓	1407 hrs. Standing water along perimeter of pond
Erosion	✓	✓	by road. Small amount of standing water behind sandbags.
Low Point, B dike*			
Flow	✓	✓	1411 hrs. Sand bags and rip rap in place. Standing
Erosion	✓	✓	water at base of slope between A and B.
Outfall water surface El. (top of stoplogs to water)			1355 hrs. Standing water behind weir. water seeping into concrete weir structure. 50". Standing water behind sandbags. No standing water. DAW

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): Standing water in road cuts. 0.05" of rain on 4/4/16.

0.19" OF RAIN ON 4/3

High Tide 2127hrs. Low Tide 1523 hrs

